SEYCHELLES PENSION FUND

FACT SHEET

PROPERTY NAME/ PARCEL	LAND USE CLASSIFICATION		17	
NO.	R7 - Medium Density Residential & Tourism			
Corail D'or Apartments				
H9102				
LOCATION	ACCESS ROAD		DATE ACQUIRED	<u>TENURE</u>
The property is situated on the coast of North East Point, not far from the Rehabilitation Centre.	Access is by a feeder road alongside the property which adjoins to the main road.		SPF purchased the land from a private owner on 22 nd March 2011.	Freehold
It is located in a "good" residential neighborhood found on left-hand side of the main road while heading north towards Glacis.				
The surrounding features include; - the main road which separates the property from the North beach; - an estate road and private properties which comprises of tourism establishments.	eyche	lles	ind	
PLOT SIZE	FLOOR AREA	AGE OF BUILDING(S)	EXPECTED REVENUE PER	DENSITY (ALLOWABLE
H9102 - 4,237m²	2 Blocks of Buildings (Ground +2 floors) Block 1 (12units) =	Construction of buildings was completed in 2016	ANNUM Approx. SCR 6,720,000.00 per	DEVELOPMEN T COVERAGE)
	2,100 m ²		year (@SCR20K-SCR25K	
	Block 2 (16units) = 2,800 m ²		per apartment per month)	
	Sub-total = 4,900 m ² Outbuilding = 50 m ² Total = 4,950 m ²			

DESCRIPTION

The property was built by SPF and consists of 2 blocks of building of similar architecture. It is being sold inclusive of existing furniture and fittings. It carries strong potentials for tourism-related activities, subject to the approval of the relevant authorities.

Existing tenancy agreements could be renegotiated or terminated by the new owners. Notice of the upcoming change in property ownership has been communicated to all tenants. The land is free from any encumbrances.

Parking

Adequate paved parking facilities for tenants are provided in the front yard of the buildings.

Security

The property is protected by a perimeter block-wall fence measuring 1.8m high and 260m long and an electronic security gate. It also has an outbuilding on the premises, which houses an electricity sub-station, a guardroom and a warden's office. Camera installation facilities are available and are in good condition.

Condition Disclosure:

The property is in good condition with minor reparation works required.

The furniture in some apartments have seen traces of wood borers, which could be treated or replaced.

